



No	Part #	Description	Application	Qty Req	Price Each
	ALH511A	Floor pan, front left		1	181.50
	ALH511B	Floor pan, front right		1	181.50
	ALH511C	Floor pan, rear left		1	269.50
	ALH511D	Floor pan, rear right		1	269.50
	ALH511E	Floor Pan, front hump		1	401.50
	ALH511F	Repair Section, front seat riser		1	434.50
	ALH511G	Repair Section, handbrake bracket		1	159.50
1	811 0823	Hood (U)	540	1	313.50
	ALH479	Hood (U)	560	1	247.50
	811 0682	Grille, hood scoop	540	1	214.50
2	ALH482	Hinge, right (U)		1	20.90
	ALH483	Hinge, left (U)		1	20.90
3	ALH493	Prop assy (U)		1	19.80
4	811 0780	Front valance (U)	540	1	126.50
	ALH488	Front valance (U)	560	1	115.50
5	ALH489	Air baffle, lower (U)		1	13.20
6	ALH490	Air baffle, right (U)		1	9.90
7	ALH491	Air baffle, left (U)		1	9.90
8	ALH492	Center support (U)		1	12.10
9	ALH500	Air baffle, upper (U)		1	21.45
10	ALH484	Fender, front right (U)		1	217.80
11	ALH484A	Repair panel, front right fender		1	109.73
12	ALH485	Fender, front left (U)		1	217.80
13	ALH485A	Repair section, front left fender		1	109.73
14	ALH636	Sill, left or right		2	87.45
	ALH636A	Sill assembly, left inner (not pictured)		1	269.50
	ALH636B	Sill assembly, right inner (not pictured)		1	269.50

No	Part #	Description	Application	Qty Req	Price Each
15	2A5227	Bracket (U)		1	20.35
16	ALH474	Roof assy (U)	542/562	1	93.50
17	ALH2540	Trunk lid (U)		1	93.50
18	ALH714	Fender, rear right (U)		1	159.50
19	ALH714A	Repair section, rear right fender		1	109.73
20	ALH715	Fender, rear left (U)		1	159.50
21	ALH715A	Repair section, rear left fender		1	109.73
22	811 0812	Door, right (U)	-E48847	1	159.50
	811 2604	Door, right (U)	E48848- no vent	1	159.50
	ALH2860	Door, right (U)	560 w/vent	1	159.50
23	811 0811	Door, left (U)	-E48847	1	159.50
	811 2603	Door, left (U)	E48848- no vent	1	159.50
	ALH2861	Door, left (U)	560 w/vent	1	159.50
24	ALH2861A	Repair section, door bottom - left or right		2	83.60
25	ALH630A	Hinge Pillar Repair Section- right side		1	357.50
	ALH631A	Hinge Pillar Repair Section - left side		1	357.50
26	ALH642A	Windshield Repair Section - right side (w/opost)		1	110.00
	ALH643A	Windshield Repair Section - left side (w/o post)		1	110.00

Floor pans and repair sections manufactured by KMC make rust repair easy.

Note: Availability of items marked (U) varies.