

PARTS FOR UNCOMMON ANTIQUE BRITISH VEHICLES & VINTAGE AIRCRAFT



Questions? Call 1-888-243-0440



SEARCH

Please include Make & Model inside SEARCH box

DELLOW PARTS

[Cooling](#)

[Electrical](#)

[Fuel and Filters](#)

[Engine](#)

Note: Not all parts are listed on this site as this is a work-in-progress site. If you don't find what you are looking for, please call toll-free, 888-243-0440 for assistance.

[Back to Uncommon British Vehicles](#)



Toll Free Order Line (US and Canada) (888) 243-0440
Information / International 011+ (972) 243-0440

[Kip Motor Home](#) | [Main Menu](#) | [Berkeley](#) | [Metropolitan](#) | [English Ford](#) | [Hillman](#) | [London Taxi](#) | [Uncommon British Vehicles](#) | [Vintage Aircraft](#) |

[Backorders](#) | [Core Charges](#) | [Returns](#) | [Shipping](#) | [Warranty](#) | [Email Kip Motor](#)

Our mission is to ensure that yesterday's antique or collector vehicle can be restored, maintained and preserved for current and future generations.

© Copyright Kip Motor Company 2007-2022 [Privacy Statement](#)
Kip Motor Company | 2127 Crown Rd | Dallas, Texas 75229 | (972) 243-0440

Powered by King Cart Services

PARTS FOR UNCOMMON ANTIQUE BRITISH VEHICLES & VINTAGE AIRCRAFT



Questions? Call 1-888-243-0440



DELLOW COOLING



| Item No | Part # | Image | Description | App | Qty Required | Price Each | Qty to Purchase | Add to Cart |
|---------|-------------|-------|--|------|--------------|------------|--------------------------------|------------------------------------|
| | | | Water Pump (X75) Price includes a \$75 core charge that is refunded once we receive your rebuildable core. | 100E | 1 | \$250.45 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 2A801 | | Fan Belt | 100E | 1 | \$31.46 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 100E-8260-A | | Top Hose | 100E | 1 | \$75.93 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 100E-8286 | | Bottom Hose | 100E | 1 | \$42.05 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 2A774 | | Water Pump (X95) Price includes a \$95 core charge that is refunded once we receive your rebuildable core. | 93A | 1 | \$301.31 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | E93A-8620-B | | Fan Belt | 93A | 1 | \$36.61 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | E93A-8260 | | Top Hose | 93A | 1 | \$45.25 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 93A-8286 | | Bottom Hose | 93A | 1 | \$61.23 | <input type="text" value="1"/> | <input type="button" value="Add"/> |

(X) indicates rebuilt items sold exchange only. The core charge is credited once we receive your rebuildable core. Reservoirs, servo units and hardware also available. Please call (888) 243-0440.

Toll Free Order Line (US and Canada) (888) 243-0440
Information / International 011+ (972) 243-0440

[Kip Motor Home](#) | [Main Menu](#) | [Berkeley](#) | [Metropolitan](#) | [English Ford](#) | [Hillman](#) | [London Taxi](#) | [Uncommon British Vehicles](#) | [Vintage Aircraft](#) |

[Backorders](#) | [Core Charges](#) | [Returns](#) | [Shipping](#) | [Warranty](#) | [Email Kip Motor](#)

Our mission is to ensure that yesterday's antique or collector vehicle can be restored, maintained and preserved for current and future generations.

© Copyright Kip Motor Company 2007-2022 [Privacy Statement](#)
Kip Motor Company | 2127 Crown Rd | Dallas, Texas 75229 | (972) 243-0440

Powered by [King Cart Services](#)

PARTS FOR UNCOMMON ANTIQUE BRITISH VEHICLES & VINTAGE AIRCRAFT



Questions? Call 1-888-243-0440



DELLOW ELECTRICAL



| Item No | Part # | Image | Description | App | Qty Required | Price Each | Qty to Purchase | Add to Cart |
|---------|------------|-------|---|-------------|--------------|------------|--------------------------------|---------------------|
| | 17H5243 | | Contact Set | 100E engine | 1 | \$16.89 | <input type="text" value="1"/> | Add |
| | 7H5086 | | Rotor, authentic reproduction. | 100E engine | 1 | \$26.29 | <input type="text" value="1"/> | Add |
| | 68693 | | Condensor | 100E engine | 1 | \$17.91 | <input type="text" value="1"/> | Add |
| | 100E-12116 | | Distributor Cap | 100E engine | 1 | \$119.46 | <input type="text" value="1"/> | Add |
| | 1D1963 | | Ignition Coil | 100E engine | 1 | \$139.76 | <input type="text" value="1"/> | Add |
| | 3H952 | | Starter (X) Please send in your starter to be rebuilt. Sorry, no cores are available. | 100E engine | 1 | \$275.50 | <input type="text" value="1"/> | Add |
| | 3H2744 | | Generator (X175) Price includes a \$175 core charge that is refunded once we receive your rebuildable core. | 100E engine | 1 | \$450.50 | <input type="text" value="1"/> | Add |
| | 17H5243 | | Contact Set | 93A engine | 1 | \$16.89 | <input type="text" value="1"/> | Add |
| | 7H5086 | | Rotor, authentic reproduction. | 93A engine | 1 | \$26.29 | <input type="text" value="1"/> | Add |
| | D93A-DC | | Condensor | 93A engine | 1 | \$16.31 | <input type="text" value="1"/> | Add |

| | | | | | | | |
|-----------------|---|-----------------|------------|---|----------|--------------------------------|---------------------|
| YE-12116-B |  | Distributor Cap | 93A engine | 1 | \$111.80 | <input type="text" value="1"/> | Add |
| BE-12000 | | Ignition Coil | 93A engine | 1 | \$123.12 | <input type="text" value="1"/> | Add |
| 7W-11001 | | Starter (X) | 93A engine | 1 | \$275.50 | <input type="text" value="1"/> | Add |
| E93AF/A-10000-B | | Generator (X) | 93A engine | 1 | \$275.50 | <input type="text" value="1"/> | Add |

Additional control box/voltage regulators, wiper motors, wiper arms and blades, fuse boxes, switches, keys and lock cylinders, wiring harnesses, dash and radio knobs, trafficators, headlamp rims and parts, and choke/throttle/speedometer cables are also available. Call (888) 243-0440 toll free with your Make and Model for pricing and availability.

(X) indicates rebuilt items sold exchange only. The core charge is credited once we receive your *rebuildable* core. Reservoirs, servo units and hardware also available. Please call (888) 243-0440.

[Check Out](#)

Toll Free Order Line (US and Canada) **(888) 243-0440**
Information / International **011+ (972) 243-0440**

[Kip Motor Home](#) | [Main Menu](#) | [Berkeley](#) | [Metropolitan](#) | [English Ford](#) | [Hillman](#) | [London Taxi](#) | [Uncommon British Vehicles](#) | [Vintage Aircraft](#) |

[Backorders](#) | [Core Charges](#) | [Returns](#) | [Shipping](#) | [Warranty](#) | Email [Kip Motor](#)

Our mission is to ensure that yesterday's antique or collector vehicle can be restored, maintained and preserved for current and future generations.

© Copyright Kip Motor Company 2007-2022 [Privacy Statement](#)
Kip Motor Company | 2127 Crown Rd | Dallas, Texas 75229 | (972) 243-0440

Powered by [King Cart Services](#)

PARTS FOR UNCOMMON ANTIQUE BRITISH VEHICLES & VINTAGE AIRCRAFT



Questions? Call 1-888-243-0440



DELLOW 93A ENGINE



| Item No | Part # | Image | Description | App | Qty Required | Price Each | Qty to Purchase | Add to Cart |
|---------|-----------|---|-----------------------|-----|--------------|------------|--------------------------------|---------------------|
| | CA690 | | Head Gasket Set | 93A | 1 | \$163.35 | <input type="text" value="1"/> | Add |
| | EA691 | | Conversion Gasket Set | 93A | 1 | \$116.47 | <input type="text" value="1"/> | Add |
| | 10165 | | Piston set with rings | 93A | 1 | \$875.27 | <input type="text" value="1"/> | Add |
| | 1016 | | Piston Ring Set | 93A | 1 | \$111.54 | <input type="text" value="1"/> | Add |
| | M3182 | | Main Bearing Set | 93A | 1 | \$279.51 | <input type="text" value="1"/> | Add |
| | C3015 | | Cam Bearing Set | 93A | 1 | \$312.79 | <input type="text" value="1"/> | Add |
| | T1936 | | Intake Valve | 93A | 4 | \$94.38 | <input type="text" value="4"/> | Add |
| | T1936 | | Exhaust Valve | 93A | 4 | \$94.38 | <input type="text" value="4"/> | Add |
| | E93A-6510 | | Intake Valve Guide | 93A | 4 | \$49.92 | <input type="text" value="4"/> | Add |
| | E93A-6510 | | Exhaust Valve Guide | 93A | 4 | \$49.92 | <input type="text" value="4"/> | Add |
| | 3DR52 |  | Timing chain | 93A | 1 | \$20.64 | <input type="text" value="1"/> | Add |

Not all parts are yet listed on this site. If you don't find what you are looking for please call. You may email info[at]kipmotor.com or call toll-free, 888-243-0440 for assistance.

[Check Out](#)

Toll Free Order Line (US and Canada) (888) 243-0440
Information / International 011+ (972) 243-0440

[Kip Motor Home](#) | [Main Menu](#) | [Berkeley](#) | [Metropolitan](#) | [English Ford](#) | [Hillman](#) | [London Taxi](#) | [Uncommon British Vehicles](#) | [Vintage Aircraft](#) |

[Backorders](#) | [Core Charges](#) | [Returns](#) | [Shipping](#) | [Warranty](#) | [Email Kip Motor](#)

Our mission is to ensure that yesterday's antique or collector vehicle can be restored, maintained and preserved for current and future generations.

© Copyright Kip Motor Company 2007-2022 [Privacy Statement](#)
Kip Motor Company | 2127 Crown Rd | Dallas, Texas 75229 | (972) 243-0440

Powered by King Cart Services

PARTS FOR UNCOMMON ANTIQUE BRITISH VEHICLES & VINTAGE AIRCRAFT



Questions? Call 1-888-243-0440



DELLOW 100E ENGINE



| Item No | Part # | Image | Description | App | Qty Required | Price Each | Qty to Purchase | Add to Cart |
|---------|--------|---|-----------------------|------|--------------|------------|--------------------------------|---------------------|
| | CC400 | | Head Gasket Set | 100E | 1 | \$163.35 | <input type="text" value="1"/> | Add |
| | EC400 | | Conversion Gasket Set | 100E | 1 | \$107.69 | <input type="text" value="1"/> | Add |
| | 11920 | | Piston set with rings | 100E | 1 | \$645.54 | <input type="text" value="1"/> | Add |
| | 1019 | | Piston Ring Set | 100E | 1 | \$86.52 | <input type="text" value="1"/> | Add |
| | M3162 | | Main Bearing Set | 100E | 1 | \$219.62 | <input type="text" value="1"/> | Add |
| | B4261 | | Rod Bearing Set | 100E | 1 | \$168.19 | <input type="text" value="1"/> | Add |
| | C3024 | | Cam Bearing Set | 100E | 1 | \$219.62 | <input type="text" value="1"/> | Add |
| | W2010 | | Thrust Washer Set | 100E | 1 | \$18.35 | <input type="text" value="1"/> | Add |
| | T2733 | | Intake Valve | 100E | 4 | \$52.34 | <input type="text" value="4"/> | Add |
| | T2734 | | Exhaust Valve | 100E | 4 | \$35.61 | <input type="text" value="4"/> | Add |
| | G348 | | Intake Valve Guide | 100E | 4 | \$4.99 | <input type="text" value="4"/> | Add |
| | G348 | | Exhaust Valve Guide | 100E | 4 | \$4.99 | <input type="text" value="4"/> | Add |
| | 3DR52 |  | Timing chain | 100E | 1 | \$20.64 | <input type="text" value="1"/> | Add |

Not all parts are yet listed on this site. If you don't find what you are looking for please call. You may email info[at]kipmotor.com or call toll-free, 888-243-0440 for assistance.

[Check Out](#)

Toll Free Order Line (US and Canada) (888) 243-0440
Information / International 011+ (972) 243-0440

PARTS FOR UNCOMMON ANTIQUE BRITISH VEHICLES & VINTAGE AIRCRAFT



Questions? Call 1-888-243-0440



DELLOW FUEL AND FILTERS



| Item No | Part # | Image | Description | App | Qty Required | Price Each | Qty to Purchase | Add to Cart |
|---------|-------------|---|--|------|--------------|------------|--------------------------------|------------------------------------|
| | D-FP | | Fuel Pump (X65) Price includes a \$65 core charge that is refunded once we receive your rebuildable core. | 100E | 1 | \$191.45 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 7H903 |  | Fuel Pump KIT | 100E | 1 | \$39.60 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | AUC9050 | | Carburettor | 100E | 1 | \$1311.04 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 8G2231 | | Carburettor KIT | 100E | 1 | \$79.53 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 100E-6731-A | | Oil Filter | 100E | 1 | \$12.32 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | D-FP | | Fuel Pump (X65) Price includes a \$65 core charge that is refunded once we receive your rebuildable core. | 93A | 1 | \$191.45 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 7H903 |  | Fuel Pump KIT | 93A | 1 | \$39.60 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | D-C | | Carburettor | 93A | 1 | \$1311.04 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | D-C (X) | | Carburettor (X), please send in your carb to be rebuilt. We replace throttle shaft, bushings, jets and float during rebuild. , please send in your carb to be rebuilt. We replace throttle shaft, bushings, jets and float during rebuild. | 93A | 1 | \$386.05 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | 8G2231 | | Carburettor KIT | 93A | 1 | \$79.53 | <input type="text" value="1"/> | <input type="button" value="Add"/> |
| | E93A-18660 |  | Oil Filter (X) | 93A | 1 | \$91.51 | <input type="text" value="1"/> | <input type="button" value="Add"/> |

(X) indicates rebuilt items sold exchange only. The core charge is credited once we receive your rebuildable core. We just don't clean and then put in new gaskets, we completely dis assemble carb, re-machine surfaces, ream new bushings for carb housing, install new throttle shaft, check jets to ensure correct, add all new gaskets and re assemble to original specifications. Reservoirs, servo units and hardware also available. Please call (888) 243-0440.